



S H A L I M A R

SHALIMAR LAKECITY PVT. LTD.

(Formally Known as ANS DEVELOPERS PVT. LTD.)



PROJECT PROGRESS REPORT APRIL 2026



SHALIMAR
ONEWORLD
BELVEDERE
SUITES



Artistic Impression

PROJECT BRIEF

- Project Name: Belvedere Suites
- Location: Baghamau, Gomti Nagar Extension, Lucknow
- Project RERA No: UPRERAPRJ263280
- Number of Towers: 1
- Number of Units: 90



SITE PLAN - ONE WORLD

Belvedere Suites



SITE PLAN –BELEVDERE SUITES



WORK PROGRESS REPORT



Shalimar Lakecity Pvt. Ltd. - Shalimar One World			
Construction Status of Belvedere Suites (GH-12)			
31-04-2026			
GH-12 (2B+G+28)			
S. No.	Description	Progress Status	Remark
1	Cleaning of area and uprooting of plants.	Comp.	
2	Earthwork	Comp.	
3	Stone Piling	Comp.	
4	Raft RCC Work	Comp.	
5	Structure Work		
A1	Tower Area 1st Basement Slab	Comp.	
A2	Tower Area 2nd Basement Slab	Comp.	
A3	Gr. Floor slab	Comp.	
A4	1st Floor Slab	Comp.	
A5	2nd Floor Slab	Comp.	
A6	3rd Floor Slab	Comp.	
A7	4th Floor Slab	Comp.	
A8	5th Floor Slab	Comp.	
A9	6th Floor Slab	Comp.	
A10	7th Floor Slab	Comp.	
A11	8th Floor Slab	Comp.	
A12	9th Floor Slab	Comp.	
A13	10th Floor Slab	Comp.	
A14	11th Floor Slab	Comp.	
A15	12th Floor Slab	Comp.	
A16	13th Floor Slab	Comp.	
A17	14th Floor Slab	Comp.	
A18	15th Floor Slab	Comp.	
A19	16th floor slab	Comp.	
A20	17th floor slab	Comp.	
A21	18th floor slab	Comp.	
A22	19th floor slab	Comp.	
A23	20th floor slab	Comp.	
A24	21st floor slab	Comp.	
A25	22nd floor slab	Comp.	

WORK PROGRESS REPORT

A26	23rd floor slab	Comp.	
A27	24th floor slab	Comp.	
A28	25th floor slab	Comp.	
A29	26th floor slab	Comp.	
A30	27th floor slab	Comp.	
A31	28th floor slab	Comp.	
A32	Top Slab	Comp.	
7	Internal Plaster		
C1	1st Floor	Comp.	
C2	2nd Floor	Comp.	
C3	3rd Floor	Comp.	
C4	4th Floor	Comp.	
C5	5th Floor	Comp.	
C6	6th Floor	Comp.	
C7	7th Floor	Comp.	
C8	8th Floor	Comp.	
C9	9th Floor	Comp.	
C10	10th Floor	Comp.	
C11	11th Floor	Comp.	
C12	12th Floor	Comp.	
C13	13th Floor	Comp.	
C14	14th Floor	Comp.	
C15	15th Floor	Comp.	
C16	16th Floor	Comp.	
C17	17th Floor	Comp.	
C18	18th Floor	Comp.	
C19	19th Floor	Comp.	
C20	20th Floor	Comp.	
C21	21st Floor	Comp.	
C22	22nd Floor	Comp.	
C23	23rd Floor	Comp.	
C24	24th Floor	Comp.	
C25	25th Floor	Comp.	
C26	26th Floor	Comp.	
C27	27th Floor	Comp.	
C28	28th Floor	Comp.	

WORK PROGRESS REPORT

8	Flooring		
D1	1st Floor	100%	
D2	2nd Floor	100%	
D3	3rd Floor	100%	
D4	4th Floor	100%	
D5	5th Floor	100%	
D6	6th Floor	100%	
D7	7th Floor	100%	
D8	8th Floor	100%	
D9	9th Floor	100%	
D10	10th Floor	100%	
D11	11th Floor	100%	
D12	12th Floor	100%	
D13	13th Floor	100%	
D14	14th Floor	100%	
D15	15th Floor	100%	
D16	16th Floor	100%	
D17	17th Floor	100%	
D18	18th Floor	100%	
D19	19th Floor	100%	
D20	20th Floor	100%	
D21	21st Floor	100%	
D22	22nd Floor		
D23	23rd Floor		
D24	24th Floor	80%	
D25	25th Floor	20%	
D26	26th Floor		
D27	27th Floor		
D28	28th Floor		
9	Electrical work		
E1	1st Floor	80%	
E2	2nd Floor	80%	
E3	3rd Floor	80%	
E4	4th Floor	80%	
E5	5th Floor	80%	
E6	6th Floor	80%	

WORK PROGRESS REPORT



E7	7th Floor	80%
E8	8th Floor	80%
E9	9th Floor	80%
E10	10th Floor	80%
E11	11th Floor	80%
E12	12th Floor	80%
E13	13th Floor	80%
E14	14th Floor	80%
E15	15th Floor	80%
E16	16th Floor	80%
E17	17th Floor	80%
E18	18th Floor	80%
E19	19th Floor	80%
E20	20th Floor	80%
E21	21st Floor	80%
E22	22nd Floor	80%
E23	23rd Floor	80%
E24	24th Floor	60%
E25	25th Floor	40%
E26	26th Floor	40%
E27	27th Floor	40%
E28	28th Floor	40%

Only Conducting Work Complete



PROGRESS IMAGES

AERIAL VIEW



PROGRESS IMAGES

SIDE VIEW



PROGRESS IMAGES

SIDE VIEW



PROGRESS IMAGES

SIDE VIEW



THANK YOU

